



Goodrich External Hoist for EC135

Hoist & Boom



- Hoist P/N: 44301-10-5
- TT: 185 Hours / 510 Cycles
- TBO Due: March 30, 2027 / 218 Hours Remaining
- Clutch Inspection Due: Since March 8, 2020
- (No charge by Goodrich @24-month replacement
- Boom & Support Assembly: P/N: 44307-500 10 Year Inspection Due: June 16, 2020
- Pendant: P/N: 44301-720 – Repaired & Approved for Return to Service
- Junction Box: P/N: 44301-700-1 – Repaired & Approved for Return to Service
- Condition: Very Good – No Corrosion
- Ownership: Original Owner

EC135 Hoist & Boom is subject to inspection/acceptance and do not constitute representations or warranties. Hoist and Boom acquisition is conditional upon a satisfactory purchase agreement, pre-purchase inspection and are subject to prior sale or removal from market without notice.